

Product Bulletin

Product: Oven Spindle Refurbishment

Description: On newer high capacity machines there are hundreds of oven spindles. After continuous production these spindles become dirty, bent and need components replaced. This is a time-consuming process that most plants cannot perform. By sending them to XLE we will completely disassemble, check run-out with an indicator, clean and polish. We will replace any needed components and reassemble. This process can be done to all spindles at once or in sections.

BEFORE



AFTER



Offering: Please contact us for price and delivery.

6960 Hammond Avenue SE Dutton, MI 49316
(t) 616.656.0324 (f) 616.656.0326 email: sales@xl-engineering.com

Sidel® & SBO® are the registered trademarks of Sidel. XLE is not a licensee of Sidel nor have XLE parts been approved or authorized by Sidel.