


Product Bulletin

Product: 10308157 2-Way Blow Valve Rebuild Modified Valve

Description: XL Engineering will clean and inspect all valve components for wear or damage. We will replace all seals, install a new guide bushing, install a new MAC[®] brand pilot valve, and reuse the valve adapter plate. The valve is pressure tested, packaged, and shipped. Customer's UM modified valve is required for this upgrade.



Offering: XL Engineering also offers Rebuild Kit 10308161 and Pilot Valve 33050008. Please contact us for pricing and availability.

6960 Hammond Avenue SE Dutton, MI 49316
(t) 616.656.0324 (f) 616.656.0326 email: sales@xl-engineering.com

Sidel[®] & SBO[®] are the registered trademarks of Sidel. XLE is not a licensee of Sidel nor have XLE parts been approved or authorized by Sidel.